



The way car buying should be.®

[Find a Car](#)

[Sell Us Your Car](#)

[Research](#)

[Financing](#)

[Why CarMax](#)

[Find a Store](#)

Search

MyCarMax

[Sign in](#) | [Register](#)

Your Nearest Store

Sacramento South
[Change](#) | [Contact Us](#) | [Map](#)

Sell Us Your Car!
[Schedule an appraisal](#)

[Website Feedback](#)

[Previous car](#) | [Next car](#) | [Back to search results](#)

2 people saved this car
[Set up a test drive now](#)

[Facebook](#) [Twitter](#) [Pinterest](#) [Email](#) [Print](#) [Save this car](#)



2004 Toyota Highlander Limited 4D Sport Utility

Leather Seats, 3rd Rear Seat, Sunroof(s) [more...](#)

No-haggle price **\$15,599***

Non-Transferable
 Only available at
 Sacramento/Roseville

[Estimate monthly payments](#)

Quick Glance

Miles	96K
Drive	2WD
Transmission	Automatic
Exterior	Gold
Interior	Tan
EPA Mileage	19/25 MPG
Stock #	11029500
Rating	4.5 ★★★★★

[19 reviews](#) | [Write a review](#)

VIN JTEDP21A140024857

[Free History Report](#)



(916) 774-4922
 (866) 629-0375

- [Hold This Car](#)
- [Schedule Test Drive](#)
- [Schedule Appraisal](#)
- [Schedule Appointment](#)
- [Get Financing Info](#)
- [Ask a Question](#)

Current Location
 Sacramento/Roseville
 1450 Eureka Road
 Roseville, CA 95661
[Hours and directions](#)

[View Full Screen](#)

CLICK TO ZOOM

1 of 32



Vehicle available as of 9/29/2014 9:13 PM Eastern Time

[Overview](#)

[Features](#)

[History Report](#)

[Warranty & MaxCare ESP](#)

[Pricing & Financing](#)

[Safety & Reliability](#)

[Reviews & Awards](#)

[Location](#)

[Trade-in](#)

Features

- Leather Seats
- 3rd Rear Seat
- Sunroof(s)
- Navigation System
- DVD Video System
- Tow Hitch

Pricing and Financing

We believe you shouldn't have to argue to get a fair price, which is why all of our prices are "no-haggle." You'll get a great car at a great price, without all the stress and worry of traditional used-car sales.

CarMax No-haggle price \$15,599*

safercar.gov

HOME VEHICLE SHOPPERS VEHICLE OWNERS VEHICLE MANUFACTURERS PARENTS CENTRAL

You are here: Home / Vehicle Owners VIN

Do You Have a Safety Problem or Complaint?

File a Complaint Now

Search for all Recalls, Complaints & Investigations

Recalls Look-up by VIN (Vehicle Identification Number)

Recalls FAQ

Receive Updates for Latest Recalls

Sign-up for Email Alerts

Subscribe to RSS Feeds

Resources

Databases (Flat Files)

Passenger Van Safety

Emergency Response Vehicles

Recalls Results Look-up by VIN

[Print](#)

VIN: JTEDP21A140024857
 Year: 2004 Make: TOYOTA Model: Highlander
 Number of Open Recalls: 2

NHTSA Recall Number: [11V112](#) Recall Date: February 24, 2011
 Manufacturer Recall Number: B0A

SUMMARY:

Toyota is recalling certain Model Year 2004-2006 Highlander, Highlander Hybrid, and Model Year 2004-2007 Lexus RX330, RX350, and RX400h vehicles. If the forward retention clip used to secure the floor carpet cover, which is located in front of the center console, is not installed properly the cover may lean toward the accelerator pedal and interfere with the accelerator pedal arm.

SAFETY RISK:

If this occurs, the accelerator pedal may temporarily become stuck in a partially depressed position rather than return to the idle position. A stuck accelerator pedal may result in unintended and sustained vehicle speeds and make it difficult to stop, increasing the risk of a vehicle crash.

REMEDY:

Dealers will replace the floor carpet cover with a newly designed one free or charge. Owners may contact Toyota at 1-800-331-4331.

RECALL STATUS: Recall INCOMPLETE

MANUFACTURER NOTES:

THIS RECALL DATA LAST REFRESHED: Sep 29, 2014

NHTSA Recall Number: [10V499](#) Recall Date: October 21, 2010
 Manufacturer Recall Number: A0M

SUMMARY:

Toyota is recalling certain Model Year 2005-2006 Avalon, Model Year 2004-2006 Highlander, Model Year 2004-2006 Lexus RX, and Model Year 2006 Lexus GS and IS vehicles. Brake fluid containing polymers is used that acts as lubricants for certain brake system components. If replacement brake fluid is used that does not contain such polymers, or that contains only small amounts, a part of the rubber seal located at the rear of the brake master cylinder may become dry, and the seal may curl during movement of the piston. If this occurs, a small amount of brake fluid could slowly leak from the seal into the brake booster.

SAFETY RISK:

A leak of brake fluid could lead to a change in brake pedal feel and overtime a degradation in braking performance increasing the risk of a crash.

REMEDY:

Dealers will replace the seal with a newly designed one. This service will be performed free of charge. The safety recall began on November 15, 2010. Owners may contact Toyota at 1-800-331-4331 and Lexus at 1-800-255-3987.

RECALL STATUS: Recall INCOMPLETE

MANUFACTURER NOTES:

THIS RECALL DATA LAST REFRESHED: Sep 29, 2014