

[Previous car](#)

[Next car](#)

[Back to search results](#)

5 people saved this car

[Set up a test drive now](#)



2009 Dodge 1 Cab

Tow Hitch, Cruise Control

No-haggle price **\$21,5**


5-Day Money-Back Guarantee[†]....

Clean Title Guarantee[†].....

[CarMax Quality Certified](#)

[Estimate monthly payments](#)

Quick Glance

Miles	42K
Drive	2WD
Transmission	Automatic
Exterior	Silver
Interior	Black
EPA Mileage	14/20 MPG
Stock #	11027682
Rating	4.8 

[21 reviews](#) | [Write a review](#)

VIN 1D3HB18T59S709565

[Free History Report](#)


[View Full Screen](#)

CLICK TO ZOOM

1 of 36



Vehicle available as of 9/24/2014 10:08 PM Eastern Time



- HOME
- VEHICLE SHOPPERS
- VEHICLE OWNERS
- VEHICLE MANUFACTURERS
- PARENTS CENTRAL

You are here: Home / Vehicle Owners VIN

Do You Have a Safety Problem or Complaint?

File a Complaint Now

Search for all Recalls, Complaints & Investigations

Recalls Look-up by VIN (Vehicle Identification Number)

Recalls FAQ

Receive Updates for Latest Recalls

Sign-up for Email Alerts

Subscribe to RSS Feeds

Resources

Databases (Flat Files)

Passenger Van Safety

Emergency Response Vehicles

Recalls Results Look-up by VIN

Print

VIN: 1D3HB18T59S709565

Year: 2009 **Make:** RAM **Model:** RAM QUAD CAB. 1500 4X2

Number of Open Recalls: 1

NHTSA Recall Number: [13V-038](#)

Recall Date: April 1, 2013

Manufacturer Recall Number: N08

SUMMARY:

THE REAR AXLE PINION NUT ON ABOUT 278,000 OF THE ABOVE VEHICLES MAY LOOSEN DUE TO UNDERSIZED PINION SHAFT SPLINES.

SAFETY RISK:

A LOOSE PINION NUT COULD CAUSE THE REAR AXLE TO SEIZE OR CAUSE THE DRIVESHAFT TO SEPARATE RESULTING IN A LOSS OF MOTIVE POWER. EITHER SITUATION COULD CAUSE A CRASH WITHOUT WARNING.

REMEDY:

THE REAR AXLE PINION NUT MUST BE INSPECTED. REAR AXLES FOUND WITH A LOOSE PINION NUT AND/OR A SEIZED UP REAR AXLE ASSEMBLY MUST BE RECONDITIONED. REAR AXLES WITH A 6-POINT PINION NUT THAT HAS NOT LOOSENED WILL HAVE A PINION NUT RETAINER INSTALLED. ALL REAR AXLES WITH A 12-POINT PINION NUT REQUIRE NO ADDITIONAL REPAIRS.

RECALL STATUS: Recall **INCOMPLETE**

MANUFACTURER NOTES:

THIS RECALL DATA LAST REFRESHED: Sep 29, 2014