

CARmax

The way car buying should be.

[Find a Car](#)

[Sell Us Your Car](#)

[Research](#)

[Financing](#)

[Why CarMax](#)

[Find a Store](#)

Sell Us Your Car!
[Schedule an appraisal](#)

Search

MyCarMax

[Sign in](#) | [Register](#)

Your Nearest Store

Sacramento South

[Change](#) | [Contact Us](#) | [Map](#)

[Website Feedback](#)

[Previous car](#) | [Next car](#) | [Back to search results](#)

[Facebook](#) [Twitter](#) [Pinterest](#) [Email](#) [Print](#) [Save this car](#)



2007 Toyota Tundra SR5 4D Crew Cab

Tow Hitch, Cruise Control, Auxiliary Audio Input [more...](#)

No-haggle price **\$25,998***

[Estimate monthly payments](#)

Quick Glance

Miles	56K
Drive	2WD
Transmission	Automatic
Exterior	Gray
Interior	Tan
EPA Mileage	16/20 MPG
Stock #	11150619
Rating	4.9 ★★★★★

[43 reviews](#) | [Write a review](#)

VIN 5TBEV54157S455692

[Free History Report](#)



(916) 774-4922

(866) 629-0375

- [Hold This Car](#)
- [Schedule Test Drive](#)
- [Schedule Appraisal](#)
- [Schedule Appointment](#)
- [Get Financing Info](#)
- [Ask a Question](#)

Current Location

Sacramento/Roseville
1450 Eureka Road
Roseville, CA 95661

[Hours and directions](#)

[View Full Screen](#)

CLICK TO ZOOM

1 of 33



Vehicle available as of 9/29/2014 10:16 PM Eastern Time

[Overview](#)

[Features](#)

[History Report](#)

[Warranty & MaxCare ESP](#)

[Pricing & Financing](#)

[Safety & Reliability](#)

[Reviews & Awards](#)

[Location](#)

[Trade-in](#)

Features

- Tow Hitch
- Auxiliary Audio Input
- Alloy Wheels
- Cruise Control
- Rear View Camera
- Overhead Airbags

Pricing and Financing

We believe you shouldn't have to argue to get a fair price, which is why all of our prices are "no-haggle." You'll get a great car at a great price, without all the stress and worry of traditional used-car sales.

CarMax No-haggle price **\$25,998***

safercar.gov

HOME

VEHICLE SHOPPERS

VEHICLE OWNERS

VEHICLE MANUFACTURERS

PARENTS CENTRAL

You are here: Home / Vehicle Owners VIN

Do You Have a Safety Problem or Complaint?

File a Complaint Now

Search for all Recalls, Complaints & Investigations

Recalls Look-up by VIN (Vehicle Identification Number)

Recalls FAQ

Receive Updates for Latest Recalls

Sign-up for Email Alerts

Subscribe to RSS Feeds

Resources

Databases (Flat Files)

Passenger Van Safety

Emergency Response Vehicles

Recalls Results Look-up by VIN

Print

VIN: 5TBEV54157S455692

Year: 2007 Make: TOYOTA Model: Tundra

Number of Open Recalls: 1

NHTSA Recall Number: [12V491](#)

Recall Date: October 10, 2012

Manufacturer Recall Number: COM

SUMMARY:

Toyota is recalling certain Model Year 2007-2009 Camry, Camry Hybrid, RAV4, Corolla, Corolla Matrix, Tundra, Sequoia, Highlander, Highlander Hybrid, Yaris, Scion xB, Scion xD and Pontiac Vibe vehicles. The power window master switch assemblies in some of these vehicles were built using a less precise process for lubricating the internal components of the switch assemblies. Irregularities in this lubrication process may cause the power window master switch assemblies to malfunction and overheat.

SAFETY RISK:

If the switch overheats, it may melt, possibly resulting in a fire.

REMEDY:

Toyota will notify its owners, and dealers will inspect the switch and apply a special grease that inhibits heat build up or replace any switch damaged by the defect, free of charge. Toyota owners that experience a problem with a switch should not attempt to make repairs, but should contact their Toyota dealer or the Toyota customer experience center at 1-800-331-4331. General Motors will contact the Pontiac Vibe owners affected by this recall and GM dealers will inspect and repair switches as necessary. Those owners may contact Pontiac customer care at 1-800-762-2737.

RECALL STATUS: **Recall INCOMPLETE**

MANUFACTURER NOTES:

THIS RECALL DATA LAST REFRESHED: Sep 29, 2014